

CT Scan CVPH



Client:

Champlain Valley Physicians Hospital.

Location:

Plattsburgh, NY

Project:

CVPH Medical Center conducted a joint replacement of their CT Scan and MRI. Equipment. The CT Scan replacement involved removal and replacement of the existing CT equipment, redistribution of the existing HVAC system, as well as architectural and aesthetic changes to the CT Room, associated control areas and reading rooms.

The difficulty in this project revolved around the lack of available shutdown time. No operational shutdown time was available for the initial field work and design, so it had to be accomplished between scheduled patient appointments. Total construction time was a mere two weeks, meaning that the design needed to be extremely accurate to limit any unforeseen changes which would lead to extension of the construction shutdown.

